



## Mynydd Llanhilleth Wind Farm

---

# ENVIRONMENTAL STATEMENT

## Appendix 12c – Accident Data



CRCID	Account ID	Category/Reason	Severity	Officer Assigned	Accident Date/Time	Year	Number of Vehicles	Number of Casualties	Ending	Notting	Highway Authority	Road Number	Weather Conditions	Road Type	Road Surface	Speed Limit	Light Conditions	Accession Detail	Pedestrian Crossing	Insulated Pedestrian	Insulated Motorcycle	Pedestrian Casualty	Child Casualty	Field Officer Casualty	Pedestrian Casualty	Insulated Car	Insulated Goods Vehicle	Insulated Bus	Insulated Young Rider	Longitude	Latitude	Local Authority District	Section Control	Is Prevalent	Is Amended	Web Link	X	Y																	
3587	20180104018	None	Sign	Police officer attended crash scene	July 2, 2018	2018	2	2	32000	20226	Turkey	A67	Free without high winds	Dual carriageway	Dry	30	Daylight - no street lighting present	Not at or within 20 metres of junction	No physical crossing facility within 50 metres	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0					
3588	20180104019	Other object on carriageway	Sign	Police officer attended crash scene	July 28, 2018	2018	2	1	32600	20228	Turkey	A602	Free without high winds	Roundabout	Dry	60	Daylight - no street lighting present	Roundabout	No physical crossing facility within 50 metres	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0			
3589	20180104020	None	Sign	Police officer attended crash scene	August 11, 2018	2018	2	1	32600	20228	Turkey	A602	Free without high winds	Dual carriageway	Dry	50	Daylight - no street lighting present	Roundabout	No physical crossing facility within 50 metres	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
13882	20180104018	None	Sign	Police officer attended crash scene	December 26, 2018	2018	2	1	32015	20213	Turkey	A67	Free without high winds	Roundabout	Dry	50	Daylight - no street lighting present	Roundabout	No physical crossing facility within 50 metres	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
13883	20180104019	None	Sign	Police officer attended crash scene	May 5, 2018	2018	2	1	32415	20207	Turkey	A67	Free without high winds	Dual carriageway	Dry	50	Daylight - no street lighting present	Roundabout	No physical crossing facility within 50 metres	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	
35904	20180104019	Investment with previous accident	Sign	Police officer attended crash scene	August 11, 2018	2018	4	1	32020	20427	Turkey	A67	Free without high winds	Single carriageway	Dry	40	Daylight - no street lighting present	Roundabout	No physical crossing facility within 50 metres	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	
35907	20180104019	None	Sign	Police officer attended crash scene	November 26, 2018	2018	2	1	32407	20222	Turkey	A602	Free without high winds	Roundabout	Dry	30	Daylight - no street lighting present	Roundabout	No physical crossing facility within 50 metres	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0		
40584	20180104018	None	Sign	Police officer attended crash scene	May 23, 2018	2018	2	1	32447	20240	Turkey	A602	Free without high winds	Dual carriageway	Dry	70	Daylight - no street lighting present	Roundabout	No physical crossing facility within 50 metres	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0		
40584	20180104018	None	Sign	Police officer attended crash scene	August 11, 2018	2018	2	2	32020	20427	Turkey	A67	Free without high winds	Roundabout	Dry	30	Daylight - no street lighting present	Roundabout	No physical crossing facility within 50 metres	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0		
40584	20180104018	None	Sign	Police officer attended crash scene	February 4, 2017	2017	2	2	32015	20226	Turkey	A602	Raining with high winds	Roundabout	Not at or within 20 metres of junction	50	Darkness - street lights present and in use	Roundabout	No physical crossing facility within 50 metres	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0		
40584	20180104018	None	Sign	Police officer attended crash scene	May 11, 2018	2018	2	1	32015	20226	Turkey	A602	Free without high winds	Dual carriageway	Dry	70	Daylight - no street lighting present	Roundabout	No physical crossing facility within 50 metres	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0		
40584	20180104018	None	Sign	Police officer attended crash scene	August 24, 2018	2018	2	1	32449	20244	Turkey	A602	Free without high winds	Roundabout	Dry	30	Daylight - no street lighting present	Roundabout	No physical crossing facility within 50 metres	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0		
40584	20180104018	None	Sign	Police officer attended crash scene	January 21, 2018	2018	2	1	32473	20249	Turkey	A602	Free without high winds	Roundabout	Dry	30	Daylight - no street lighting present	Roundabout	No physical crossing facility within 50 metres	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0		
40584	20180104018	None	Sign	Police officer attended crash scene	March 28, 2017	2017	2	1	32479	20249	Turkey	A602	Free without high winds	Single carriageway	Dry	60	Daylight - no street lighting present	Roundabout	No physical crossing facility within 50 metres	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0		
43762	20180104018	None	Sign	Police officer attended crash scene	November 2, 2018	2018	2	4	32015	20226	Turkey	A67	Raining with high winds	Dual carriageway	Road surface water over 30mm depth	70	Darkness - street lights present and in use	Not at or within 20 metres of junction	No physical crossing facility within 50 metres	0	0	0	0	0	0	0	0	0	1	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	
40584	20180104018	None	Sign	Police officer attended crash scene	April 9, 2018	2018	2	1	32400	20215	Turkey	A67	Free without high winds	Roundabout	Dry	70	Daylight - no street lighting present	Roundabout	No physical crossing facility within 50 metres	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	
40584	20180104018	None	Sign	Police officer attended crash scene	November 2, 2018	2018	2	1	32401	20216	Turkey	A602	Free without high winds	Roundabout	Dry	50	Daylight - no street lighting present	Roundabout	No physical crossing facility within 50 metres	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	
40584	20180104018	None	Sign	Police officer attended crash scene	July 11, 2018	2018	2	1	32401	20216	Turkey	A602	Free without high winds	Dual carriageway	Dry	60	Daylight - no street lighting present	Roundabout	No physical crossing facility within 50 metres	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	
40584	20180104018	Investment with previous accident	Sign	Police officer attended crash scene	March 23, 2018	2018	2	3	32479	20249	Turkey	A602	Free without high winds	Roundabout	Dry	30	Daylight - no street lighting present	Roundabout	No physical crossing facility within 50 metres	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	
40584	20180104018	None	Sign	Police officer attended crash scene	December 14, 2018	2018	2	1	32000	20225	Turkey	A602	Free without high winds	Roundabout	Not at or within 20 metres of junction	70	Daylight - no street lighting present	Roundabout	No physical crossing facility within 50 metres	0	0	0	0	0	0	0	0	0	0	1	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	
40584	20180104018	None	Sign	Police officer attended crash scene	February 24, 2018	2018	2	1	32407	20222	Turkey	A602	Free without high winds	Roundabout	Dry	70	Daylight - no street lighting present	Roundabout	No physical crossing facility within 50 metres	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	
40584	20180104018	None	Sign	Police officer attended crash scene	June 6, 2018	2018	2	1	32000	20225	Turkey	A602	Free without high winds	Roundabout	Dry	70	Daylight - no street lighting present	Roundabout	No physical crossing facility within 50 metres	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	
40584	20180104018	None	Sign	Police officer attended crash scene	November 1, 2018	2018	2	2	32006	20226	Turkey	A67	Free without high winds	Single carriageway	Dry	40	Daylight - no street lighting present	Not at or within 20 metres of junction	No physical crossing facility within 50 metres	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
40584	20180104018	None	Sign	Police officer attended crash scene	May 28, 2018	2018	2	1	32400	20215	Turkey	A602	Free without high winds	Roundabout	Not at or within 20 metres of junction	70	Daylight - no street lighting present	Roundabout	Central verge - no other controls	0	0	0	0	0	0	0	0	0	1	1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
40584	20180104018	None	Sign	Police officer attended crash scene	March 9, 2018	2018	2	1	32471	20248	Turkey	A67	Free without high winds	Single carriageway	Dry	50	Daylight - no street lighting present	Roundabout	No physical crossing facility within 50 metres	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	
40584	20180104018	None	Sign	Police officer attended crash scene	January 16, 2017	2017	2	3	32400	20215	Turkey	A67	Free without high winds	Dual carriageway	Dry	70	Daylight - no street lighting present	Roundabout	No physical crossing facility within 50 metres	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	
40584	20180104018	None	Sign	Police officer attended crash scene	January 9, 2018	2018	2	1	32400	20215	Turkey	A602	Free without high winds	Dual carriageway	Wet or Damp	50	Daylight - no street lighting present	Roundabout	No physical crossing facility within 50 metres	0	0	0	0																																

*This page is intentionally blank*

